The display cable runs through the hinge and fails with repeated opening, producing flicker or a dead panel. Replacing it *lenovo laptop repair services nairobi* alongside a stiff hinge prevents a repeat. Cable notes at %LINK%.